

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	IS&R	L1	6	(("4473045") or ("4977862") or ("5065705") or ("5133303") or ("5343970") or ("5555871")) .PN.	USPA T	2002/06/2 1 08:37	
2	BRS	L2	1	1 and hybrid	USPA T	2002/06/2 1 08:38	
3	BRS	L3	1	2 and (overheat temperature)	USPA T	2002/06/2 1 08:41	
4	BRS	L4	1878	hybrid near3 (vehicle car drive automobil locomotive)	USPA T	2002/06/2 1 10:14	
5	BRS	L5	96	4 and overheat\$4	USPA T	2002/06/2 1 09:27	
6	BRS	L6	1782	4 not 5	USPA T	2002/06/2 1 09:27	
7	BRS	L7	24255	engine near3 temperature	USPA T	2002/06/2 1 09:28	
8	BRS	L8	241	6 and 7	USPA T	2002/06/2 1 09:29	
9	BRS	L9	97	8 and coolant	USPA T	2002/06/2 1 10:10	
10	BRS	L10	144	8 not 9	USPA T	2002/06/2 1 10:27	
11	BRS	L11	1571	(cooling coolant) near5 failure	USPA T	2002/06/2 1 10:16	
12	BRS	L12	0	10 and 11	USPA T	2002/06/2 1 10:13	
13	BRS	L13	5253	hybrid near3 (vehicle car drive automobil locomotive)	EPO; JPO; DERW ENT	2002/06/2 1 10:15	
14	BRS	L14	733	(cooling coolant) near5 failure	EPO; JPO; DERW ENT	2002/06/2 1 10:16	
15	BRS	L15	1	13 and 14	EPO; JPO; DERW ENT	2002/06/2 1 10:16	
16	BRS	L16	7	10 and (range near3 extend\$4)	USPA T	2002/06/2 1 10:28	

	Error Definition	Er ro rs
1		0
2		0
3		0
4		0
5		0
6		0
7		0
8		0
9		0
10		0
11		0
12		0
13		0
14		0
15		0
16		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
17	IS&R	L17	89	(("4080947") or ("4134261") or ("4146006") or ("4227505") or ("4276863") or ("4292938") or ("4459951") or ("4629471") or ("3775745") or ("4549504") or ("4755790") or ("4790280") or ("4887068") or ("4930475") or ("4940965") or ("4971583") or ("5016006") or ("5020497") or ("3623568") or ("3719881") or ("3792327") or ("4008423") or ("4165795") or ("4187436") or ("4301396") or ("4305254") or ("4306156") or ("4313080") or ("4335429") or ("4363999") or ("4691148") or ("4730151") or	USPA T	2002/06/2 1 10:40	
18	BRS	L18	35	17 and hybrid	USPA T	2002/06/2 1 10:49	
19	BRS	L19	54	17 not 18	USPA T	2002/06/2 1 10:49	

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	IS&R	L1	6	((("4473045") or ("4977862") or ("5065705") or ("5133303") or ("5343970") or ("5555871"))).PN.	USPA T	2002/06/2 1 08:37	
2	BRS	L2	1	1 and hybrid	USPA T	2002/06/2 1 08:38	
3	BRS	L3	1	2 and (overheat temperature)	USPA T	2002/06/2 1 08:41	
4	BRS	L4	1878	hybrid near3 (vehicle car drive automobil locomotive)	USPA T	2002/06/2 1 10:14	
5	BRS	L5	96	4 and overheat\$4	USPA T	2002/06/2 1 09:27	
6	BRS	L6	1782	4 not 5	USPA T	2002/06/2 1 09:27	
7	BRS	L7	24255	engine near3 temperature	USPA T	2002/06/2 1 09:28	
8	BRS	L8	241	6 and 7	USPA T	2002/06/2 1 09:29	
9	BRS	L9	97	8 and coolant	USPA T	2002/06/2 1 10:10	
10	BRS	L10	144	8 not 9	USPA T	2002/06/2 1 10:27	
11	BRS	L11	1571	(cooling coolant) near5 failure	USPA T	2002/06/2 1 10:16	
12	BRS	L12	0	10 and 11	USPA T	2002/06/2 1 10:13	
13	BRS	L13	5253	hybrid near3 (vehicle car drive automobil locomotive)	EPO; JPO; DERW ENT	2002/06/2 1 10:15	
14	BRS	L14	733	(cooling coolant) near5 failure	EPO; JPO; DERW ENT	2002/06/2 1 10:16	
15	BRS	L15	1	13 and 14	EPO; JPO; DERW ENT	2002/06/2 1 10:16	
16	BRS	L16	7	10 and (range near3 extend\$4)	USPA T	2002/06/2 1 10:28	